


INSTALLATION OF DRIVERS FOR THE JA-80T (PC-60B) INTERFACE IN THE WINDOWS XP OPERATING SYSTEM


First of all it is necessary to prepare the whole installation

- Download the drivers from the attached CD/DVD or from the internet onto the hard drive in your PC or into a special folder. The downloaded file must be unpacked first – it was packed by WinRar software – extract it into the same folder
- Then you can connect the JA-80T interface to the requested (the best solution is a free one) USB port on the computer
- The new-hardware installation wizard is then triggered


Windows XP




The Installation Wizard asks you if you want to download the drivers from the internet
Choose NO, NOT NOW
Next >




Install from list or exact position (for specialists)
Next >




Don't search, choose a driver for installation
Next >



- Now you have to choose a type of hardware
Ports (COM and LPT)
Next >




From floppy drive (flash disk)...




Browse...

- If you open the right folder, you can see 4 files and a file called Jablbis.inf in "Name of a file"


Search file - Open




Installation from floppy disk drive (flash disk) – OK




Next >



Continue



- Windows is installing the drivers




Finish

- This procedure will run again with the same steps



- After successful installation, a bubble will appear with the text : hardware is ready to use.
 - Check the drivers
 - My PC – Options – Hardware – Device Manager**
- In the “COM and LPT” menu you should see “JABLOTRON serial interface device” and in the USB bus as well.



- If everything seems to be OK, look into:
Start – Options – Control Panel – Add or Remove Programs
- There should be JABLOTRON serial interface in alphabetical order

